



Major Aircraft Service Changes and Modifications Incorporated:

ASC102A Main Entry Door Handle Modification (Part 2)
 ASC155 Axle Cap MLG Strut
 ASC162A AM1 Navigation Position Lights – LED
 Navigation Light Installation
 ASC 163 DL950 Data Loader Installation
 ASC 173A Water Line Ribbon Heater Upgrade
 ASC 179A Micro Quick Access Recorder Installation
 ASC186B IAC FMS 6.1 Software with SBAS/LPV GPS
 Installation
 ASC 189 Modification - Wing Rear Beam – Flight
 Spoiler Actuator Attachment Point
 ASC 192A Automatic Dependence Surveillance
 Broadcast Out (ADS-B Out v1 - DO-260A)

ASC 197A Stage 4 Noise Standards - Certification Aileron
 ASC 199A Cable Fairleads at Sponson Rib - Installation
 Landing Gear Door Close – Restrictor
 ASC 200B Aileron & Elevator Power Disconnect -
 ASC 202A Removal
 ASC 204 Aileron Cable Penetrations at FS 576.5
 Floor Beam – Rework
 ASC 206 Elevator Hardover Prevention System
 (HOPS) – Improvement
 ASC 210B Nose Landing Gear (NLG) Harness -
 Installation
 ASC 212 Engine Driven Pump (EDP) Case Drain
 Hose Routing In Left Pylon

Avionics:

Dual Honeywell SPZ-8500 AFCS
 Honeywell SPZ-8500 FCS EFIS
 Honeywell / GEC Marconi Heads-Up Display (HUD) w/ Enhanced
 Vision System (EVS)
 2Collins VHF-422C VHF Comm Tranceivers w/ 8.33 spacing
 3 Collins VIR-432 VHF NAV Receivers
 3Honeywell AV-850 Digital Audio Panels
 2 Collins ADF-462 ADF's
 2 Collins DME-422 DME's
 2Collins TDR-94D Mode S Transponders w/ ADS-B Out v1
 (DO260A)
 3 Honeywell CD-830 CDU's
 3 Honeywell NZ-2000 FMS (IAC) w/ 6.1 Software
 2 Honeywell HG2021KB02 GPS Sensors (SBAS / WAAS Certified)
 3 Honeywell LaserRef III IRS
 1 Honeywell Mark V EGPWS w/ RAAS & Windshear Warning
 System

2 Honeywell RT-300 Radio Altimeters
 1 Honeywell Primus 880 Weather Radar
 1 Honeywell DL 950 Data loader
 3 Honeywell AZ-840 Micro Air Data Computers
 1 Artex 406 MHz ELT
 2 Collins RM-855 Radio Management Units w/ Color CDU's
 2 Collins HF-9000 HF Communication w/ SELCAL
 1 SELCAL Decoder
 1 Cockpit Printer
 1 Honeywell AFIS/SAT AFIS
 Fairchild Cockpit Voice Recorder (CVR)
 Flight Data Recorder (FDR)
 Micro QAR for Forms FOQA Data
 1 Honeywell MCS-6000 SATCOM



800+

Aircraft Transactions to Date



50+

Years in the Industry



\$10+ Billion

In Aircraft Transactions

aircraftsales@leas.com
201.891.0881 | LEAS.COM

Additional Miscellaneous Equipment:

Dual EVAS
Electronic Clocks
Collins Airshow 500
Therapeutic Oxygen Outlet
Pulselights
Tail Logo Lights
21" LCD Monitor in the Right-Hand Fwd Cabin Bulkhead
21" LCD Monitor in the Right-Hand Aft Cabin Bulkhead

Maintenance:

Engines enrolled on Rolls-Royce CorporateCare
Enrolled on MSG-3 Program and Gulfstream CMP Maintenance Tracking Program
Heavy maintenance performed primarily at Gulfstream Service Centers
Majority of CMP Codes Due:

- 12 Mos due 08/31/19
- 24 Mos due 08/31/19
- 48 Mos due 09/30/21
- 72 Mos due 02/28/22
- 96 Mos due 09/30/21
- 144 Mos due 04/30/26
- 192 Mos due 04/30/30

Weight & Balance:

Basic Empty Weight: 47,530 Lbs.
Basic Operating Weight: 48,808 Lbs.
Max Ramp Weight: 90,900 Lbs.
Max Takeoff Weight: 90,500 Lbs.

Interior:

Complete NEW Interior Installed April 2017 by Cabin Crafters – Hackensack, NJ

April 2017: Extensive Interior Refurbishment to include:

Replacement of all soft goods in Cockpit, Crew Seats, Main Entrance, Galley, Crew Rest, Fwd Lavatory, Main Cabin (club seats, divan, headliners, valence panels, window panels, dado panels, PSU panels), and Aft Lavatory.

Replaced cockpit curtain, acoustical weather curtain, and crew rest curtain.

Custom cut and installed new main entrance steps.

Installed 8 new single club seats.

Replaced all carpeting throughout entire aircraft.

Replaced Fwd-Cabin, Mid-Cabin and Aft-Cabin Bulkheads.

Complete refurbishment of fwd galley and aft main lavatory to include new countertops, faucets, vanity, and drawer inserts.

Installed LED cabin lighting throughout the cabin.

Re-plated all visible hardware.

Stripped and replaced veneer on all cabinetry, side ledges, tables, and hardwood edging surfaces.

Installed New Collins Venue HD Cabin Management System with CD/Blu-ray Disc Player, and two 21" LCD Video Monitors (one on the RS Forward bulkhead and one on the RS Aft Bulkhead).

New Airshow 500.

iPad and iPhone controls.

Dual USB charging stations at each cockpit seat and at every cabin seat.

The 14 passenger interior with crew jump seat features a **forward galley, forward crew rest area**, forward crew lavatory, aft main lavatory, and aft baggage compartment. The entry area includes the forward full-service main galley on the right-hand side, galley annex on the left-hand side, forward crew lavatory on the right-hand side, and forward crew rest area on the left-hand side. The entry area and fwd-cabin are separated by a swinging door. The fire-blocked interior features a forward-cabin 4-place club (the right forward-facing seat is designated as VIP seat), a mid-cabin 4-place club, and an aft-cabin stateroom with a left-hand side 2-place club opposite a 4-place berthable divan separated from the mid-cabin by a bulkhead with pocket door. Shades are electronically operated.

Interior Continued:

The 8 club chairs are upholstered in a Spinneybeck light tan leather, the divan in a complementing Loro Piana light tan designer fabric, complemented by a neutral tan/brown carpet (replaced May 2017). The headliner and PSU panels are ivory ultra leather, the dados are covered in light tan leather, the window reveals are a light tan textured linen fabric, the galley countertop is a pine colored speckled corian material, and the interior woodwork and cabinetry finished in a dark cherry high gloss veneer. All exposed cabin functional and decorative metal surfaces, latches, and fixtures are plated in a brushed nickel finish. Multiple 115VAC/60Hz outlets are located throughout the cockpit and main cabin for crew and passenger use. The window The forward and mid-cabin 4-place clubs include manually operated fold-out executive tables between the opposing club chairs, the 2 forward-facing club seats in the forward-cabin have full size fold out footrests and the club sections are berthable.

Cabin entertainment includes High Speed Data access via Aircell ATG-4000 Gogo Biz® Hi-Speed Internet Service w/ Talk & Text and ViaSat Mobile Broad Band Multi-Link (BBML) KU Band High Speed Data System. Airshow 500 and a CD/Blu-ray Disc Player can be viewed on two 21" LCD Video Monitors (one on the RS Forward bulkhead and one on the RS Aft Bulkhead). The forward full-service main galley features a microwave oven, high-temp oven, coffee maker, galley sink with cold/hot potable water, dual ice drawers, cold storage drawer, and ample miscellaneous storage drawers and compartments for crystal, china, flatware and condiments.

Exterior:

Long Beach, CA

Painted September 2011 @ Gulfstream –

Overall Matterhorn White with Spring Mills Blue, Snow White, Gamma Gray, and Kingston Gray Stripping.

Location:

Aircraft is Located at Morristown Municipal Airport (MMU), in Morristown, NJ, USA.



800+

Aircraft Transactions to Date



50+

Years in the Industry



\$10+ Billion

In Aircraft Transactions

aircraftsales@leas.com
201.891.0881 | LEAS.COM



800+

Aircraft Transactions to Date



50+

Years in the Industry



\$10+ Billion

In Aircraft Transactions

aircraftsales@leas.com
201.891.0881 | LEAS.COM



800+
Aircraft Transactions to Date



50+
Years in the Industry



\$10+ Billion
In Aircraft Transactions

aircraftsales@leas.com
201.891.0881 | LEAS.COM









800+
Aircraft Transactions to Date



50+
Years in the Industry



\$10+ Billion
In Aircraft Transactions

aircraftsales@leas.com
201.891.0881 | LEAS.COM



800+
Aircraft Transactions to Date



50+
Years in the Industry



\$10+ Billion
In Aircraft Transactions

aircraftsales@leas.com
201.891.0881 | LEAS.COM



800+
Aircraft Transactions to Date



50+
Years in the Industry



\$10+ Billion
In Aircraft Transactions

aircraftsales@leas.com
201.891.0881 | LEAS.COM



800+

Aircraft Transactions to Date



50+

Years in the Industry



\$10+ Billion

In Aircraft Transactions

aircraftsales@leas.com
201.891.0881 | LEAS.COM





Frank Janik

frank@leas.com

Cell: 862-222-0820

Office: 201-891-0881

35 Waterview Blvd. 2nd FL. Parsippany, NJ 07054
aircraftsales@leas.com | 201.891.0881 | LEAS.COM